

578 Missing Icons

Hi guys,

Correcting missing or corrupt icons on the D578 is easy, it uses the same icon update pack that the D878 uses. The current icon file is Icon v1.20, which was included as part of 878 firmware v1.11 release.

The process is:

1. Turn D578 off
2. Connect USB cable to radio and PC
3. Hold in P1 & Channel dial button, while turning the radio on.
4. Almost immediately the screen displays "UPDATE MODE" - if not, try again.
5. Start up 578 CPS, select appropriate COM port under Set > Set COM menu.
6. Go to Tool then Firmware Upgrade (yes, that is correct)
7. Point the software to the 878 Icon v1.20 file
8. Again, select the appropriate COM port.
9. Hit Write button. Writing should take no more than 55 seconds.
10. Power off the D578, remove USB cable, power on. All done, no need to reset.

Thanks,
Jason

Download this file and unzip.

All you need is the folder called [D878UV_ICONV1.20_0226](#)